

**OFFICE OF THE SUB-DIVISIONAL ENGINEER,
Construction Sub-Division No. 2, PWD B&R Branch, Bathinda**

E-mail: sdec2pwdbti@gmail.com

To,

Executive Engineer,
Provincial Division,
PWD B & R Branch, Bathinda.

Memo No.: 668

Date: 25/09/2026



Subject: Regarding issuance of School Building Safety Certificate for the year 2026-27 -
The Vibgyor School, Ramgarh Bhundar, District Bathinda.

Reference: Regarding for Your office letter No.2533 date-05/06/20226

With reference to the subject cited above and the letter under reference, it is reported that the building of the above-mentioned school was inspected on site by the undersigned along with Ms. Manpreet Kaur, J.E. The said building appears to be safe for normal conditions up to 31-03-2027. Therefore, the Building Safety Certificate for the year 2026-27 of the above-mentioned school is hereby recommended for issuance, subject to the following conditions:

1. The school shall have a proper disaster/emergency management plan to deal with any unforeseen disaster. The plan must include arrangements for safely evacuating the children from the building during an emergency and for coordination with the concerned departments. The school shall regularly review and update the plan to ensure its effectiveness.
2. If the school intends to carry out or has carried out any addition, alteration, extension or modification in the building, immediate inspection by this office shall be arranged, and after completion of the said work, the safety certificate for the concerned portion shall again be obtained from this office.





3. If the walls, foundations or roofs of the building settle or suffer damage due to any natural disaster or any other reason, the school shall immediately inform this office regarding the condition of the building. The building shall be brought into use only after inspection has been carried out.

4. A separate Fire Safety Certificate and Electrical Safety Certificate shall be obtained from the concerned departments.

5. Keeping in view the safety of the school building, the responsibility for carrying out necessary repairs to the building shall rest with the school management. Notwithstanding this report, the school management shall remain responsible for the safety of the building in all respects.

6. Nirman Architects, vide Letter No. 2901 dated 29-01-2026, have issued the safety certificate for the school mentioned above. As per their certificate, the school for the academic year — The school is considered safe for use during the year 2026-27. However, since the construction of this school was not carried out by this Department, the structural safety of the school, particularly from the earthquake point of view, cannot be assured by this Department.

7. The school staff members should be provided with appropriate safety training, including procedures for handling emergency first aid and evacuation protocols.

8. An amount of Rs.5,000/- towards the school inspection fee, as applicable according to the covered area of the school, has been deposited by the Divisional Office vide GR No.358417 dated 05-06-2026.

9. The school shall be responsible for getting its Fire Safety Certificate renewed in time.

10. This report is not valid for legal purposes.

This is being forwarded to you for your information and for taking further necessary action, please.

Enclosure: Case in original (in duplicate).

Sub-Divisional Engineer,

Construction Sub-Division No. 2,

B & R Branch, Bathinda



Attested to be true translation
from *Punjabi* To *English*

MANISH GARG
Notary & Advocate
(Appointed by Govt. of India)
Bathinda (PB.)

26 SEP 2026